

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program April 16, 2012

Reviewed:	MY
KCVICWCU.	

Mine Name: Italian Tan	Permit Number: S/007/0038		
Operator Name: Quality Building Stone	Inspection Date: 04/04/2012		
Inspector(s): Wayne Western	Time: 9:00- 9:45 AM		
Other Participants:	Mine Status: ACT		
Weather Condition: Cool and clear skies	Last Inspection: 3/30/2011		
Bond Renewal Date: 07/22/2006	Bond Amount: \$12,500		
Surface Ownership: Fee	Mineral Ownership: Fee		

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds		\boxtimes	
2.	Annual Fees	$\overline{\boxtimes}$	$\overline{\boxtimes}$	
3.	Public Safety (shafts, adits, trash, signs, highwalls)			
4.	Protection of Drainages / Erosion Control			
5.	Deleterious Material			
6.	Roads (maintenance, surfacing, dust control, safety)			
7.	Concurrent Reclamation			
8.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
9.	Water Impoundments			
10.	Soils			П
11.	Re-vegetation			
12.	Air Quality			
13.	Annual Report			
14.	Other			

Purpose of Inspection:

This was a bond release inspection.

Inspection Summary:

The site Permittee requested a partial bond release at the site.

After the inspection, I showed Paul Baker pictures of the site. Paul Baker and I compared the photographs taken during the inspection with those taken before reclamation. There is one section of the area that was not reclaimed and has rills and gullies. The Division contacted Velina Miller, she claims that the site was left according to instructions given them by the landowner, Utah Railway.

Inspection Date: April 4, 2012

Page 2 of 5 S/007/0038

On April 16, 2012, the Wayne Western talked to Andy Chunko of Utah Railway. Mr. Chunko was unaware of the reclamation activities on site. The Division agreed to send him a copy of this inspection report and the Notice of Intent.

The permit fees were not paid for 2011. I checked with Paul Baker, since the site is in reclamation permit fees are not due.

The site is safe for the public. There are no shafts, adits, trash or highwalls on the site. There is no mining activity on the site.

The Permittee installed diversion ditches to prevent erosion on the reclaimed roads. Non road areas were pocked to control erosion and promote vegetation.

There were no deleterious materials on site.

The main roads were reclaimed. The roads were left in a condition so that the landowner could still access them. The roads had diversion ditches to reduce erosion and associated rills and gullies. The road will be evaluated at final reclamation.

The earthwork was completed. The roads had water diversion structures installed to prevent formation of rills and gullies. The other areas were had been pocked.

your as be ter

The Permittee seeded the area during reclamation, which was in the early spring.

The Permittee did not submit an annual report for 2011.

Conclusions and Recommendations:

The Division will wait to hear from the landowner prior to granting final bond release.


Inspector's Signature

WHW:

cc: (OPERATOR)

agencies


O:\M007-Carbon\S0070038-ItalianTan\inspections\Insp-04042012.doc



Road reclaimed



Roads reclaimed.




Pocked area and boulder placement.



Disturbed area that was not reclaimed.



Picture taken May 5, 2005 shows that area was not disturbed as of that date.



Picture taken November 18, 2004 shows the area had not been disturbed as of that date.